



RTS weekly lookahead Week commencing 19/08/2024




Updated or amended details are in **RED**

Location Description	Reason for works	Impacts	Mitigations (if applicable)
Via Urbis / Mill Road to Dickenson Road (within the site boundaries)	Works to North east corner of Mill Road (New Kerb Alignment, Tactiles and Traffic signal ducting)	Footpath closure for the safety of pedestrians Pedestrians accessing east side of Mill road will need to cross NAR and rejoin as per the plan	Diversion route as shown on the ped diversion plan
Via Urbis / Mill Road to Dickenson Road (within the site boundaries)	Traffic signal and street light ducting / Excavation of roadbox and capping/ subbase fill. Drainage works to existing AW assets	None	N/A
Via Urbis / Mill Road to Dickenson Road (within the site boundaries)	Footpath/ cycleway formation and subbase /kerbing/traffic signals ducting	None	N/A
Dickenson Road to Wallace Road (within the site boundaries)	installation of kerbs on Footway/ Cycleway	None	N/A
Dickenson Road to Wallace Road (within the site boundaries)	footway/cycleway formation & Subbase Traffic signals ducting Base & Binder Surfacing on Bus Lane.	None	N/A
Wallace Road to Bruff Close	Traffic signals ducting Accoustic fencing Excavation fill for new bus lane	None	N/A
Wallace Road to Bruff Close	Drainage installation	None	N/A
Via Urbis / Mill Road to Dickenson Road (within the site boundaries)	Drainage/kerbing/signals ducting	Traffic will be unable to turn left into Mill Road when heading northbound on the A134 (Northern Approach Road)	Road users should continue northbound along the A134 and continue north along Via Urbis Romanae until reaching the roundabout with Axial Way. They will need to return south along Via Urbis Romanae / A134 and turn right into Mill Rd west.

Via Urbis / Mill Road footway closure – The footpath highlighted red will be closed for the kerb alignment and tactiles for the new crossing.

Pedestrians needing to access the eastern side of Mill Road will need to cross Northern Approach Road and follow the route below marked by the green dashes





The no left turn into Mill Road from Northern Approach needs to be installed again for ongoing works to the kerbing and signals ducting. This will enable pedestrians to cross Northern Approach Road (A134) whilst the eastern side of Mill Road footway is closed