Castle Point Local Highway Panel Meeting Agenda

13th June 2013 16:00hrs Committee Room 1, Castle Point Council Offices.

Panel Members:

ECC Councillors
Dave Blackwell
Ray Howard
Jill Reeves
Alan Bayley
Jamie Huntman

CPBC Councillors

Other Attendees:

ECC:

Sean Perry - Principal Area Transportation Co-ordinator Natalie Szpigelman - Highways Liaison Officer Gary Webster - Road Safety Engineer Tony Buston- Strategy & Engagement Officer

CPBC:

Trudie Bragg - Head of Environment Stuart Jarvis – Contracts Manager Cheryl Salmon- Civic Governance Officer

Time		Item	Lead:	Papers:
	1	Welcome and Introductions	SP	Verbal
	2	Election of Chairman and District Members	SP	Verbal
	3	Approval of Minutes of Last Meeting 26 th February 2013	SP	Verbal
	4	Local Highways Panels- Budget and Remit	NS/SP	Attached
	5	Potential Schemes for Consideration of Panel Inc. Casualty Reduction Schemes	GW/NS	Attached
	6	Hadleigh Town Regeneration	ТВ	To Follow
	7	Indicative Start Dates for 2012-13 LHP Schemes	NS	Attached
	8	Dutch Village Estate- Maintenance of Un-adopted Road	RH	Verbal
	9	AOB		
	10	Date of next meeting- 5 th September		

CASTLE POINT LOCAL HIGHWAYS PANEL – MINUTES AND ACTIONS						
		PRESENT:				
Date: 26 th February 2013 Venue: Committee Room 1, Castle Point Council Offices, Benfleet		Panel Members: Cllr Bill Dick (Chairman) (BD), Cllr Ray Howard (RH), Cllr Jill Reeves (JR), Cllr Colin Riley (CR), Cllr Dave Blackwell (DB), Cllr Jackie Govier (JG), Cllr Simon Hart (SH), Cllr Martin Tucker (MT) and Cllr Tom Skipp (TS).				
	ogies: ian Wood	Other Attendees: Sean Perry – Principal Area Transportation Co-ordinator (SP), Natalie Szpigelman – Highways Liaison Officer (NS) Rosemary Wilkins – Cycling Officer (RW), Gary Webster – Safety Engineer (GW), Trudie Bragg – CPBC Head of Environment (TB), Stuart Jarvis – CPBC Contracts Manager (SJ), Cheryl Salmon – Minute Taker				
Item:	Action:		Action Owner:			
1.	Welcome and Introductions	ne and Introductions				
2.	Declarations of Interest: Cllr Dick disclosed an interest un Potential Schemes for Consider governor at Robert Drake Primary					
3.	Minutes of meeting held on 6 th D Agreed.					
	Somnes, Avenue, Canvey Island	– Crossing				
	The Panel was unhappy that the so RH as Deputy Cabinet Member to	RH				
4.	Kents Hill Road Pedestrian Cros					
	SP reported the scheme had been providing the engineer was satisfisite next year. CR queried wheth well. SP stated that this may have	SP/NS				
5.	Foksville Road Casualty Reduct	ion Scheme				
	· ·	uty lorries had problems at this junction. nel agreed that officers should investigate				

report back on proposed	signage may a	ld not be signalised and it will discuss some of the issues. GV			
Potential Schemes for consideration of the Panel: Minor Schemes					
Scheme:	Estimated Cost:	Action:			
Robert Drake Primary, Thundersley – New guardrail	£5k - £10k	Agreed	NS/SF		
Newlands Road, Canvey Island - Bollards	′	Agreed			
Romsey Road, Benfleet Traffic calming	-	Provide update to be included in the minutes	SP		
Kents Hill Road North, Benfleet – Bollards or other preventative measures		Agree to fund but continue to investigate other preventative measures.	SP		
Cycling Schemes	Fstimated	Action:]		
Cycling Schemes Scheme: Benfleet Station – Inadequate cycle parking	Estimated Cost: 20k	Action: Investigate costings	RW		
Scheme: Benfleet Station – Inadequate cycle parking Holy Family Church - Ci	Cost: 20k cossing the crossing in B				
Scheme: Benfleet Station – Inadequate cycle parking Holy Family Church - Co	Cost: 20k cossing the crossing in B	Investigate costings			
Scheme: Benfleet Station – Inadequate cycle parking Holy Family Church - Cr CR reported problems at dropping off children at A	Cost: 20k cossing the crossing in Repleton School.	Investigate costings			

BD stated that there were outstanding issues at the junction particularly with regard to the right-hand turn. SP reported that it was planned to undertake a video survey of the junction in May 2013 over a 24hr period to assess any remaining issues. Canvey Way, Slip Road RH reported that the slip road was dangerous and needed to be looked at. Waterside Farm, Canvey Island – Pedestrian Crossing SP to provide update to be included in the minutes Common Hall Lane/New Road Junction, Hadleigh JR reported that drivers regularly pulled out on the wrong side of New Road to turn into Common Hall Lane rather than queue at the traffic lights. SP to investigate. Delfzul Road, Canvey Island – Crossroads DB reported that there had been a number of accidents in this area. The Panel agreed that road markings at all the junctions in the surrounding area should be repainted. NS to investigate costings. Benfleet High Road TS requested that due to speeding issues in the High Road traffic calming measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		Tarpots Junction, Benfleet	
RH reported that the slip road was dangerous and needed to be looked at. Waterside Farm, Canvey Island – Pedestrian Crossing SP to provide update to be included in the minutes Common Hall Lane/New Road Junction, Hadleigh JR reported that drivers regularly pulled out on the wrong side of New Road to turn into Common Hall Lane rather than queue at the traffic lights. SP to investigate. Delfzul Road, Canvey Island – Crossroads DB reported that there had been a number of accidents in this area. The Panel agreed that road markings at all the junctions in the surrounding area should be repainted. NS to investigate costings. Benfleet High Road TS requested that due to speeding issues in the High Road traffic calming measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. 10. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		BD stated that there were outstanding issues at the junction particularly with regard to the right-hand turn. SP reported that it was planned to undertake a video survey of the junction in May 2013 over a 24hr period to assess any	SP
Waterside Farm, Canvey Island – Pedestrian Crossing SP to provide update to be included in the minutes Common Hall Lane/New Road Junction, Hadleigh JR reported that drivers regularly pulled out on the wrong side of New Road to turn into Common Hall Lane rather than queue at the traffic lights. SP to investigate. Delfzul Road, Canvey Island – Crossroads DB reported that there had been a number of accidents in this area. The Panel agreed that road markings at all the junctions in the surrounding area should be repainted. NS to investigate costings. Benfleet High Road TS requested that due to speeding issues in the High Road traffic calming measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. 10. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		Canvey Way, Slip Road	
SP to provide update to be included in the minutes Common Hall Lane/New Road Junction, Hadleigh JR reported that drivers regularly pulled out on the wrong side of New Road to turn into Common Hall Lane rather than queue at the traffic lights. SP to investigate. Delfzul Road, Canvey Island – Crossroads DB reported that there had been a number of accidents in this area. The Panel agreed that road markings at all the junctions in the surrounding area should be repainted. NS to investigate costings. Benfleet High Road TS requested that due to speeding issues in the High Road traffic calming measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. 10. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		RH reported that the slip road was dangerous and needed to be looked at.	
Common Hall Lane/New Road Junction, Hadleigh JR reported that drivers regularly pulled out on the wrong side of New Road to turn into Common Hall Lane rather than queue at the traffic lights. SP to investigate. Delfzul Road, Canvey Island – Crossroads DB reported that there had been a number of accidents in this area. The Panel agreed that road markings at all the junctions in the surrounding area should be repainted. NS to investigate costings. Benfleet High Road TS requested that due to speeding issues in the High Road traffic calming measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		Waterside Farm, Canvey Island – Pedestrian Crossing	
JR reported that drivers regularly pulled out on the wrong side of New Road to turn into Common Hall Lane rather than queue at the traffic lights. SP to investigate. Delfzul Road, Canvey Island – Crossroads DB reported that there had been a number of accidents in this area. The Panel agreed that road markings at all the junctions in the surrounding area should be repainted. NS to investigate costings. Benfleet High Road TS requested that due to speeding issues in the High Road traffic calming measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		SP to provide update to be included in the minutes	SP
to turn into Common Hall Lane rather than queue at the traffic lights. SP to investigate. Delfzul Road, Canvey Island – Crossroads DB reported that there had been a number of accidents in this area. The Panel agreed that road markings at all the junctions in the surrounding area should be repainted. NS to investigate costings. Benfleet High Road TS requested that due to speeding issues in the High Road traffic calming measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		Common Hall Lane/New Road Junction, Hadleigh	
DB reported that there had been a number of accidents in this area. The Panel agreed that road markings at all the junctions in the surrounding area should be repainted. NS to investigate costings. Benfleet High Road TS requested that due to speeding issues in the High Road traffic calming measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. 10. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		to turn into Common Hall Lane rather than queue at the traffic lights. SP to	SP
Panel agreed that road markings at all the junctions in the surrounding area should be repainted. NS to investigate costings. Benfleet High Road TS requested that due to speeding issues in the High Road traffic calming measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. 10. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		Delfzul Road, Canvey Island – Crossroads	
TS requested that due to speeding issues in the High Road traffic calming measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. 10. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		Panel agreed that road markings at all the junctions in the surrounding area	NS
measures, including VAS signs should be investigated. NS to look into. Rangers Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		Benfleet High Road	
Following discussion the view of the Panel was that CPBC should take over responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. 10. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		·	NS
responsibility for the co-ordination of the Rangers. SP and TB to work with Peter Massey to find a way forward. 10. Date of next meeting It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		Rangers	
It was reported that two dates had been set for 2013/14 as follows: Thursday 13 th June 2013		responsibility for the co-ordination of the Rangers. SP and TB to work with	SP/TB
Thursday 13 th June 2013	10.	Date of next meeting	
		It was reported that two dates had been set for 2013/14 as follows:	
Thursday 5 th September 2013		Thursday 13 th June 2013	
		Thursday 5 th September 2013	