

## **Gt Notley Humpback Bridge 4055**

Gt Notley Humpback Bridge carries the highway over a balancing pond, which takes water from the surrounding Great Notley Garden Village. After a general inspection, it was observed that the four corners of the bridge had experienced scour / erosion. The method for repair to this bridge was undertaken by using plastic sheet piles and bamboo kingposts.

The scheme was completed in in March 2017.



Before works Photo 1



Before works Photo 2



Bamboo Photo



Bamboo Being installed Photo
















After works Photo 2



The engineer on this scheme visited Notley Green Primary school shortly after completion of the scheme and gave a safety presentation to the school children and this scheme was on the agenda as part of the presentation and it was well received by all at the school.





