

## Pitsea Flyover 1072 – drainage works

Part of the maintenance works to Pitsea Flyover was a drainage clear out and investigation scheme which was completed over 5 nights under full road closure. During this work removal of loose concrete was also carried out during the road closure.



During works photo 1



During works photo 2



Before drainage clearance photo



After drainage clearance photo

As you can see from the photos above the need for a road closure as this work would not be able to go ahead with the road open.