

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|--------------|-------------------|--------------------------|----------------------------------------------------------------------------------------|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|-------------------|----------------------------|-----------------|
| LUTT19-06-30 | Arkesden | Duddenhoe End Road | CB11 4HG | Other (explain in notes) | Flood/Test your brakes sign fallen over | | | | |
| LUTT19-06-31 | Arkesden | | | Sign cleaning | Clean all road signs at entrance to and within the village | | | | |
| LUTT19-06-32 | Arkesden | B1039/Long Lane junction | | Other (explain in notes) | Sign to "Newland End" missing | | | | |
| LUTT19-06-33 | Arkesden | | CB11 4HB to CB11 4EX | Grass | Cut back grass along edges of footpath | | | | |
| LUTT19-06-34 | Arkesden | Various | | Other (explain in notes) | Replace damaged or missing reflector posts | | | | |
| LUTT19-06-35 | Arkesden | Various | | Painting | Clean and re treat public benches | | | | |
| LUTT19-06-39 | Arkesden | | | | 4. Edge the footpath between the village hall , CB11 4HB and The Old Post Office, CB11 4EX, and between Honeybrook House and Long Thatches also CB11 4EX. | | | | |
| LUTT19-06-40 | Arkesden | | | | 6. Clean and re-treat 9 public wooden benches in the village. | | | | |
| LUTT19-06-18 | Ashdon | Radwinter Road | Junction with new house Lane | RSDM | x3 fingerpost sign dislodged and dirty JOB FOR RANGERS | 3375580 | 30/05/2019 | | |
| LUTT18-06-01 | Aythorpe Roding | Bigods Road | Jw Loves Lane. | Sign cleaning | Finger post directional sign dirty. | 3220914 | 03/05/2018 | 10/09/2018 | COMPLETE |
| LUTT18-07-01 | Aythorpe Roding | B184 | Gunners Green to Axe PH | Weeding | clear vegetation growing over path | | 22/06/2018 | | |
| LUTT18-10-01 | Aythorpe Roding | Throughout the village | Vegetation covering footpaths and drains | Vegetation trimming | all through the 30mph area | | 03/09/2018 | | |
| LUTT19-06-37 | Aythorpe Roding | B184 | junction Drury Lane/B184 behind bus shelter | Vegetation trimming | Parish Council to repair and repaint bus shelter | | | | |
| LUTT18-10-02 | Barnston | Chelmsford Road | Either end of the village | Vegetation trimming | The village signs are obscured by vegetation | | 09/09/2018 | | |
| LUTT19-06-10 | Barnston | High Easter Road | Jw Chelmsford road | OGRO | RANGERS Ra4=1x4 overgrown brush making hard to see coming out of Plowden close | 3340301 | 07/03/2019 | | |
| LUTT19-06-29 | Barnston | Chelmsford Road | Barnston | Vegetation trimming | When leaving Barnston Village Hall you are unable to see oncoming traffic from the left as the bushes are over grown. | | | | |
| LUTT18-07-02 | Berden | Pelham Road | Pathway to Parkers | Vegetation trimming | | | 22/06/2018 | COULDN'T FIND THE LOCATION | UNSUITABLE |
| LUTT18-07-04 | Berden | Blakings Lane | Near The Crump | Vegetation trimming | | | 22/06/2018 | 10/10/2018 | COMPLETE |
| LUTT18-07-05 | Berden | Berden Road | Junction with Rickling Road | Vegetation trimming | Lack of visibilty at junction | | 22/06/2018 | 10/10/2018 | COMPLETE |
| LUTT18-07-06 | Berden | Rickling Road | Crossroads Berden-Rickling Road and Manuden-Clavering Road | Vegetation trimming | Lack of visibilty at junction | | 22/06/2018 | 10/10/2018 | COMPLETE |
| LUTT19-06-41 | Berden | Bonnetting Lane | The pathway leading up to the 4 houses on the left as you foirst enter Bonnetting Lane | Vegetation trimming | Vegetation is encroaching the pathway making it difficult for the residents to use | | | | |
| LUTT19-06-42 | Berden | Pelham Road | The path leading up to Gawlers | Painting | The railings need to be repainted | | | | |
| LUTT18-07-07 | Birchanger | Birchanger Lane | Cambridge Road and Hillside Cottages | Vegetation trimming | vegetation encroaching on the footpath | | 19/06/2018 | | |
| LUTT18-08-04 | Birchanger | | REQUEST FOR PARISH VISIT | | Angie Driscoll - 07778 856080 | | 25/07/2018 | 28/02/2019 | COMPLETE |
| LUTT18-10-72 | Birchanger | Stansted Road | Footpath between bus shelter and entrance to Sion Park. | Vegetation trimming | Footway Overgrown. Approx 100m. 40mph limit, but remote from Cway. | 3280439 | 05/11/2018 | 04/03/2019 | COMPLETE |
| LUTT19-01-86 | Birchanger | Dunmow Road | From bus layby to roundabout. | OGRO | Vegetation Overgrown onto Fway. Approx 15m x 1m. | 3312782 | 04/01/2019 | 18/03/2019 | COMPLETE |

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|--------------|---------------|------------------------|------------------------------------------------------------------|--------------------------|----------------------------------------------------------------------------------------------------------------------------------|----------------|----------------|----------------|----------|
| LUTT18-07-10 | Chrishall | Throughout the village | | Sign cleaning | all signs and street furniture to be cleaned | | 14/06/2018 | 09/10/2018 | COMPLETE |
| LUTT18-10-27 | Chrishall | Mill Causeway | Jw Crawley End. | Sign cleaning | Directional finger post sign dirty. | 3237220 | 25/06/2018 | 31/12/2018 | COMPLETE |
| LUTT18-10-28 | Chrishall | Mill Causeway | Jw Abrams Lane. | Sign cleaning | Directional finger post sign dirty. | 3237222 | 25/06/2018 | 04/02/2019 | COMPLETE |
| LUTT19-01-07 | Clavering | Starlings Green | | Sign cleaning | ADHIC JOB - Refurbish finger post | PARISH VISIT | | 08/01/2019 | COMPLETE |
| LUTT19-01-08 | Clavering | The Druce | Opposite The Druce | Other (explain in notes) | ADHOC JOB - Reinstall post that had been knocked down | PARISH VISIT | | 08/01/2019 | COMPLETE |
| LUTT18-06-41 | Clavering | London Road | Opp Fox and Hounds | Other (explain in notes) | Repair for railings by the river | | | 06/12/2018 | Complete |
| LUTT18-06-49 | Clavering | Deers Green | | Other (explain in notes) | Dig out a grip and cleaning out the pipe going into the river | | | 29/11/2018 | COMPLETE |
| LUTT18-06-53 | Clavering | Clavering Village Hall | | Other (explain in notes) | Cleaning of path outside Village Hall | | | 19/11/2018 | COMPLETE |
| LUTT18-06-54 | Clavering | throughout the village | | Sign cleaning | Sign Cleaning around Village and Litter Pick | | | 21/11/2018 | COMPLETE |
| LUTT18-07-11 | Clavering | Langley Road | Jw Shepcote Green. | Sign cleaning | Directional finger post sign dirty. | 3232843 | 13/06/2018 | 19/03/2019 | COMPLETE |
| LUTT18-07-12 | Clavering | Langley Road | Jw Mill Lane.n | Sign cleaning | Directional finger post sign dirty. | 3232842 | 13/06/2018 | 19/03/2019 | COMPLETE |
| LUTT18-07-13 | Clavering | Langley Road | Jw Valence Road. | Sign cleaning | Directional finger post sign dirty. | 3232841 | 13/06/2018 | 28/02/2019 | COMPLETE |
| LUTT18-08-05 | Clavering | | REQUEST FOR PARISH VISIT | | Richard Carter - 01799 550364 | | 25/07/2018 | 10/12/2018 | COMPLETE |
| LUTT18-07-14 | Debden | High Street | The footpath opposite The Plough | Vegetation trimming | The footpath leading to the rec is overgrown | | 30/06/2018 | 18/03/2019 | COMPLETE |
| LUTT18-10-48 | Debden | Water Lane | 15 m from Electricity pole 92 | Vegetation trimming | veg obstructing junction signs view on both sides of the road | 3254556 | 13/08/2018 | 18/03/2019 | COMPLETE |
| LUTT18-10-49 | Debden | Water Lane | 4m from Electricity pole 92 | Vegetation trimming | veg obstructing junction signs view on both sides of the road | 3254557 | 13/08/2018 | 18/03/2019 | COMPLETE |
| LUTT19-01-11 | Duddenhoe End | School Lane | At the junction with Bull Lane | Painting | Fingerpost needs refurbishing | | 28/11/2018 | | |
| LUTT18-08-16 | Elmdon | Heydon Lane | at the top of the Lane | Other (explain in notes) | The fingerpost needs to be refurbished | | 31/07/2018 | | |
| LUTT18-10-25 | Elmdon | Hertford Lane | Jw Mill Causeway | Sign cleaning | Directional finger post sign dirty. | 3237187 | 25/06/2018 | 02/11/2018 | COMPLETE |
| LUTT18-01-62 | Elsenham | Elsenham Road | Jw Dukes Orchard. | Sign cleaning | School sign dirty. | 3177619 | 13/12/2017 | 25/02/2019 | COMPLETE |
| LUTT18-06-02 | Elsenham | Elsenham Road | Jw Green street | Sign cleaning | Directional finger post dirty. | 3222401 | 10/05/2018 | 25/02/2019 | COMPLETE |
| LUTT18-07-17 | Elsenham | Stansted Road | Elsenham | Vegetation trimming | Hedge is encroaching Fway. as is just within 30mph limit | 3236990 | 22/06/2018 | | COMPLETE |
| LUTT19-01-16 | Elsenham | Station Road | Between Ridley Gardens and Orchard Crescent | Vegetation trimming | Please would you cut back the growth of nettles and bramble ect. This path is much used by children going to the primary school. | | 19/10/2018 | | |
| LUTT19-06-08 | Elsenham | Stansted Road | From LC 11 to opp jw Gilbey Cottages. | FWDF | Ra4 = 1 x 4. Verge encroaching Fway making it narrow for pushchairs. Approx 40m. Rangers. | 3330210 | 13/02/2019 | | |
| LUTT18-08-12 | Elsenham | Station Road | By the entance of De Mandeville Road down to the station | Vegetation trimming | One resident has recently had his head cut by overhanging brambles | | 03/08/2018 | 12/10/2018 | COMPLETE |
| LUTT18-08-13 | Elsenham | Stansted Road | Hedge outside Langtons | Vegetation trimming | overgrown hedge is encroaching onto the footway | | 13/08/2018 | 11/10/2018 | COMPLETE |
| LUTT18-08-14 | Elsenham | Stansted Road | Near the mini roundabouts by the shops, opposite the bus shelter | Vegetation trimming | The hedge is overhanging the path | | 13/08/2018 | 11/10/2018 | COMPLETE |
| LUTT18-10-69 | Elsenham | Stansted Road | Opp jw Leigh Drive. | Sign cleaning | Directional road signs dirty. | 3275934 | 24/10/2018 | 21/02/2019 | COMPLETE |
| LUTT18-06-03 | Farnham | Hazeland Road | Jw Hazel End Lane. | Sign cleaning | Directional finger post dirty. | 3225496 | 21/05/2018 | 10/10/2018 | COMPLETE |
| LUTT18-06-52 | Farnham | Walnut Tree Lane | | Other (explain in notes) | Clear out culvert | | | 30/11/2018 | COMPLETE |
| LUTT19-01-93 | Farnham | Chatter End Road | Immediately to the right of school entrance. | DEB | Ditch filled in. Approx 2m x 1m x 1m. Has recent drainage work taken place? | 3324034 | 29/01/2019 | 28/02/2019 | COMPLETE |
| LUTT18-06-05 | Felsted | Braintree Road | Opp entrance to Oakley Villas. | Vegetation trimming | Vegetation Overgrown around base of sign. Unable to access inspection cover. | 3222928 | 11/05/2018 | | |

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|--------------|-------------------|---------------------|-------------------------------------------------------------------------------------------|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|----------------|----------------|----------|
| LUTT18-10-47 | Felsted | Watch House Green | Just past the bend bannister green felsted sign | Vegetation trimming | overgrown veg is blocking the sign up to 50% | 3252590 | 09/08/2018 | 20/02/2019 | COMPLETE |
| LUTT19-01-77 | Felsted | Watch House Green | Just past the bend bannister green felsted sign | Vegetation trimming | overgrown veg is blocking the sign up to 50% | 3290272 | 16/11/2018 | | COMPLETE |
| LUTT18-07-18 | Great Canfield | | REQUEST FOR PARISH VISIT | Other (explain in notes) | Parish Visit contact Parish Clerk, Allison Ward 01245 231798 | | 18/06/2018 | | COMPLETE |
| LUTT18-10-51 | Great Chesterford | Walden Road | 100m from Jackson lane | Vegetation trimming | Ra3=1x3 roadsign for 50mph obscured by veg | 3254853 | 14/08/2018 | | |
| LUTT19-06-01 | Great Chesterford | Ickleton Road | From beggining of junction to the beggining of bridge | OGRO | Ra2=2x1 overgrown vegetation 30 m length job for rangers | 3264946 | 18/09/2018 | | |
| LUTT18-01-58 | Great Dunmow | Kerridge Close | Jw New Road. | Sign cleaning | finger post directional sign dirty. | 3161263 | 16/10/2017 | 25/02/2019 | COMPLETE |
| LUTT18-06-07 | Great Dunmow | Kerridge Close | Jw Dunmow bypass - | Vegetation trimming | Hedge Overgrown. Signs obscured by vegetation. | 3225061 | 18/05/2018 | | COMPLETE |
| LUTT18-06-08 | Great Dunmow | Dunmow Bypass | From roundabout with Chelmsford Road to safety barrier South of River Chelmer. West side. | Vegetation trimming | Hedge Overgrown. Signs obscured by vegetation. | 3225068 | 18/05/2018 | 06/09/2018 | COMPLETE |
| LUTT18-06-11 | Great Dunmow | Chelmsford Road | Rear of Picture Framing Art House. | Vegetation trimming | Fway Overgrown . Approx 50m both sides. | 3216303 | 23/04/2018 | 06/09/2018 | COMPLETE |
| LUTT18-06-12 | Great Dunmow | Braintree Road | Jw Dunmow bypass. West side. Approx 100m. | Vegetation trimming | Hedge Overgrown. Signs obscured by vegetation. | 3225087 | 18/05/2018 | 10/10/2018 | COMPLETE |
| LUTT18-07-19 | Great Dunmow | St Edmunds Fields | Great Dunmow | Weeding | weeds are over growing and starting to make footway smaller | 3236248 | 21/06/2018 | 28/03/2019 | COMPLETE |
| LUTT18-07-20 | Great Dunmow | The Avenue | Great Dunmow | Weeding | over grown tree over hanging the footway by 50% | 3234960 | 18/06/2018 | 28/03/2019 | COMPLETE |
| LUTT18-06-10 | Great Dunmow | Dunmow Bypass | From jw Stortford Road to approx 200m west of jw. North side of Cway. | Vegetation trimming | Hedge Overgrown. Signs obscured by vegetation. | 3225043 | 18/05/2018 | | |
| LUTT18-10-30 | Great Dunmow | The Avenue | Outside number 2 | Vegetation trimming | tree is over grown taking up the whole pathway | 3240042 | 04/07/2018 | | |
| LUTT18-10-71 | Great Dunmow | The Mead | Outside house number 14 | Vegetation trimming | bush is growing up and is obstructing the view for the restandent when pulling in to there driveway Flow of school children sometimes. Bush needs about 0.8/1 meter taken off the top | 3278031 | 31/10/2018 | | |
| LUTT19-06-02 | Great Dunmow | The Causeway | Walkway next to 148 152 flats | OGRO | RANGERS weeds growing out the edge of the pathway coving 20% of the pathway | 3270652 | 08/10/2018 | | |
| LUTT19-06-26 | Great Dunmow | Ash Grove | foot bridge over the Stream | Vegetation trimming | | | | | |
| LUTT19-06-27 | Great Dunmow | Highfields | Highfields to standrums foot path | Vegetation trimming | | | | | |
| LUTT19-06-28 | Great Dunmow | White Street | White St to Randall Close foot path | Vegetation trimming | | | | | |
| LUTT19-06-43 | Great Dunmow | Bypass | Approaching Tesco roundabout | Grass | | | | | |
| LUTT19-01-06 | Great Dunmow | Woodland Park Drive | All along the bypass | Other (explain in notes) | ADHIC JOB - litter picking and verge repairs | | | 07/01/2019 | COMPLETE |
| LUTT19-01-09 | Great Dunmow | Stebbing Road | at the junctions | Illegal sign removal | ADHOC JOB - remove estate agent boards which are causing visibility issues | | | 09/01/2019 | COMPLETE |
| LUTT19-05-08 | Great Dunmow | Barnston Road | Coming off trhe A120 slip road | Vegetation trimming | ADHOC JOB - Safety cut at the junction to provide visibility for vehicles leaving the A120 | | | 22/05/2019 | COMPLETE |
| LUTT19-05-09 | Great Dunmow | Kerridge Close | at the junction | Vegetation trimming | ADHOC JOB - Safety cut at the junction | | | 22/05/2019 | COMPLETE |
| LUTT19-05-12 | Great Dunmow | Chelmsford Road | At the junction with the B1008 | Vegetation trimming | ADHOC JOB - Safety cut at the junction | | | 22/04/2019 | COMPLETE |

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|--------------|--------------------|------------------------|-------------------------------------------------------------------------------|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|----------------|----------------|----------|
| LUTT18-06-14 | Great Easton | Breach Lane | Approx 20m north of jw Mill End Green Road. | Sign cleaning | Speed limit signs dirty. | 3227301 | 30/05/2018 | 19/02/2019 | COMPLETE |
| LUTT18-07-21 | Great Sampford | Sampford Hall Lane | Great Sampford | Sign cleaning | Directional finger post sign dirty. | 3232383 | 12/06/2018 | | |
| LUTT18-06-42 | Hadstock | Hadstock Village Green | | Vegetation trimming | Tidy up trees from the phone box to pump | | | 26/11/2018 | Complete |
| LUTT18-06-43 | Hadstock | Hadstock Village Green | | Other (explain in notes) | Cleaning of phone box inside and out | | | 26/11/2018 | Complete |
| LUTT18-06-44 | Hadstock | Hadstock Village | Within 30mph limit | Vegetation trimming | Trimming vegetation around signs and cleaning of signage | | | 26/11/2018 | Complete |
| LUTT18-06-45 | Hadstock | Hadstock Village | | Vegetation trimming | Strim around the stones on the village green | | | 26/11/2018 | COMPLETE |
| LUTT18-06-46 | Hadstock | Main Linton Road | | Other (explain in notes) | Litter picking | | | 26/11/2018 | COMPLETE |
| LUTT18-06-47 | Hadstock | Main Linton Road | | Vegetation trimming | Cut back vegetation around the of park | | | 26/11/2018 | COMPLETE |
| LUTT18-06-48 | Hadstock | Moules Lane | | Footway drainage channel cleaning | Clean out the drain at the end of the road | | | 28/11/2018 | COMPLETE |
| LUTT19-01-05 | Hadstock | | On the village Green | Painting | ADHOC JOB - Refurbishing bench | PARISH VISIT | | 23/01/2019 | COMPLETE |
| LUTT18-10-70 | Hadstock | Bartlow Road | At side of Symantha cottage | Vegetation trimming | overgrown veg 10mtrs | 3277244 | 29/10/2018 | | |
| LUTT19-06-09 | Hadstock | Bartlow Road | At side of Symantha cottage | OGRO | Ra4=2x2 overgrown veg 10mtrs JOB FOR RANGERS | 3335518 | 26/02/2019 | | |
| LUTT18-06-55 | Halingbury | | | Vegetation trimming | Trimming of tree left across the path | | | 21/11/2018 | COMPLETE |
| LUTT19-01-90 | Hatfield Broad Oak | Feathers Hill | Opp Ivy Cottage | RSOB | 30mph repeater sign obscured by vegetation. | 3314895 | 09/01/2019 | | |
| LUTT18-10-35 | Hatfield Broad Oak | High Street | Jw Cage End. | Sign cleaning | Directional finger post sign dirty. | 3242915 | 11/07/2018 | 18/02/2019 | COMPLETE |
| LUTT18-10-68 | Hatfield Broad Oak | High Street | From opp Duke's Close to opp Duke's Head pub. | Vegetation trimming | Hedge encroaching Fway. Approx 100m. | 3275183 | 22/10/2018 | 26/02/2019 | COMPLETE |
| LUTT18-07-22 | Hatfield Heath | Sheering Road | The path leading from the speed limit terminal sign in the Sheering direction | vegetation trimming | Vegetation is encroaching onto the footpath and reducing the available width for the pedestrians to walk on | | 14/06/2018 | | |
| LUTT18-10-59 | Hatfield Heath | Sawbridgeworth Road | From opp 5 Gladwyns Cottage to guard rails. | Vegetation trimming | Vegetation encroaching Fway. Siding. 30mph. Approx 50m. | 3267367 | 25/09/2018 | 26/02/2019 | COMPLETE |
| LUTT19-01-84 | Hatfield Heath | Sawbridgeworth Road | From opp 5 Gladwyns Cottage to guard rails. | OGRO | Vegetation encroaching Fway. Siding. 30mph. Approx 50m. | 3311035 | 03/01/2019 | 27/02/2019 | COMPLETE |
| LUTT19-06-44 | Hempstead | | REQUEST FOR PARISH VISIT - David Drane (07504 696656) | | | | | | |
| LUTT18-10-50 | Hempstead | Bumpstead Road | From direction of Haverhill near j/w Harvey Way, and Coach Rd | Vegetation trimming | 30mph /speed restriction area sign obscured by vegetation | 3254815 | 14/08/2018 | 19/03/2019 | COMPLETE |
| LUTT18-10-03 | Henham | Chickney Road | Field View close along Chickney Road | Other (explain in notes) | Vegetation clearance and litter picking in and around the ditches from Fieldview Close along Chickney Road as far as the footpath leading up to the Rugby Club. | | 15/10/2018 | | |
| LUTT18-10-04 | Henham | High Street | All village ponds | Other (explain in notes) | Vegetation clearance and litter picking in and around all village ponds | | 15/10/2018 | | |
| LUTT19-01-14 | Henham | Chickney Road | Field View close along Chickney Road | Other (explain in notes) | Vegetation clearance and litter picking in and around the ditches from Fieldview Close along Chickney Road as far as the footpath leading up to the Rugby Club. | | 15/10/2018 | | |

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|--------------|------------------|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|-------------------------------------------------------------------------------------|----------------|----------------|----------------|----------|
| LUTT19-01-15 | Henham | High Street | All village ponds | Other (explain in notes) | Vegetation clearance and litter picking in and around all village ponds | | | | |
| LUTT19-06-04 | Henham | Thaxted Road | Jw Plegdon green Lane. | RSOB | Directional finger post sign dirty. Rangers. | 3273166 | 16/10/2018 | | |
| LUTT18-10-46 | Henham | School Lane | From opp no 1 Sages towards School Lane. | Vegetation trimming | Vegetation encroaching Fway. Approx 30m. | 3251506 | 07/08/2018 | | COMPLETE |
| LUTT18-07-24 | High Easter | | REQUEST FOR PARISH VISIT | Other (explain in notes) | Parish Visit contact Parish Clerk, Allison Ward 01245 231798 | | 17/06/2018 | | COMPLETE |
| LUTT18-10-05 | High Roding | All | Pavements | Weeding | Please can you spray the weeds! Many thanks | | 19/09/2018 | | |
| LUTT19-06-38 | High Roding | | Behind the Black Lion pub leading towards High Roding | Vegetation trimming | | | | | |
| LUTT19-01-02 | Langley | Duddenhoe End Road | | Other (explain in notes) | ADHOC JOB - Repaired and painted railings | PARISH VISIT | | 28/01/2019 | COMPLETE |
| LUTT19-01-03 | Langley | | Outside The Bull Pub | Verge repair | ADHOC JOB - digging out ditch, creating new grips, dig out 3 gullies | PARISH VISIT | | 29/01/2019 | COMPLETE |
| LUTT19-01-04 | Langley | | | Other (explain in notes) | ADHOC JOB - refurbishing village benches | PARISH VISIT | | 22/01/2019 | COMPLETE |
| LUTT18-08-18 | Langley | Langley Lower Green | Near Potterells cottage | Other (explain in notes) | Repair and painting of damaged railings (hit by a car) at bridge over river Stort. | | 09/07/2018 | 25/03/2019 | COMPLETE |
| LUTT18-08-19 | Langley | Langley Lower Green | REQUEST FOR PARISH VISIT | | Mrs Carol Elkington - 01799 550729 | | 09/07/2018 | | COMPLETE |
| LUTT19-05-01 | Langley | Mill Road | At the junction with Langley Road | Other (explain in notes) | ADHOC JOB - reinstall finger post that has been refurbished | ALDEN ROAD | | 22/05/2019 | COMPLETE |
| LUTT19-05-02 | Langley | Uppr and Lower | | Other (explain in notes) | ADHOC JOB - repaint two benches | | | 20/05/2019 | COMPLETE |
| LUTT18-08-17 | Leaden Roding | Stortford Road (A1060) | Opposite Leaden Roding Village Hall | Vegetation trimming | Clearance of vegetation | | 16/07/2018 | 03/07/2018 | COMPLETE |
| LUTT18-08-02 | Leaden Roding | Dunmow Road | Opposite the school up to the Keeres Green junction | Vegetation trimming | Vegetation overhanging the footpath is impeding the available space for pedestrians | | 02/08/2018 | | |
| LUTT18-07-25 | Lindsell | Holders Green Road | Lindsell | Sign cleaning | Speed limit signs dirty. | 3227286 | 30/05/2018 | 19/02/2019 | COMPLETE |
| LUTT18-06-21 | Lindsell | Duck End Farm Lane | Jcnw Holders Green Rd. | Sign cleaning | Finger post dirty. | 3227284 | 30/05/2018 | 19/02/2019 | COMPLETE |
| | Lindsell | Duck End Farm Lane | Jcnw Holders Green Rd. | RSOB | Ra2 = 1 x2. Finger post dirty. Rangers. | 3227284 | 30/05/2018 | | |
| LUTT18-06-19 | Lindsell | Lindsell Lane | Jw Great Easton Road. | Other (explain in notes) | Directional finger post missing. | 3202391 | 13/03/2018 | | |
| LUTT18-08-08 | Little Bardfield | Throughout the village | | Sign cleaning | road sign cleaning | | 13/07/2018 | 04/04/2019 | COMPLETE |
| LUTT18-06-24 | Little Bardfield | Dunmow Road | Jw Fanns Farm Lane. | Sign cleaning | Directional finger post sign dirty. | 3230713 | 07/06/2018 | | |
| LUTT18-08-09 | Little Bardfield | | | Vegetation trimming | cut back vegetation by speed camera | | 13/07/2018 | | |
| LUTT18-08-10 | Little Bardfield | Styles | The roadsides in Styles | Vegetation trimming | Tidied especially from Furthermoor House to past the salt bin. | | 13/07/2018 | | |
| LUTT19-01-82 | Little Bardfield | Little Sampford Road | junction of bardfield rd | RSOB | Directional finger post sign dirty. | 3299935 | 05/12/2018 | | |
| LUTT18-10-54 | Little Canfield | High Cross Lane | Jw Bacon End Road. | Sign cleaning | Graffiti on sign. | 3255891 | 17/08/2018 | 21/02/2019 | COMPLETE |
| | Little Canfield | High Cross Lane | Jw Bacon End Road. | RSOB | Ra4 = 1 x 4 . Graffiti on sign. Rangers. | 3255891 | 17/08/2018 | | |
| LUTT18-10-06 | Little Canfield | Public Footpaths | B1256 opposite Lion and Lamb Pub footpath B1256 between the Lion and Lamb and Buttonseed Meadow (where the lane goes up to Little Canfield Hall, opposite Church Lane | clearing foot paths / cutting thorn branches etc | clearing foot paths / cutting thorn branches | | 18/09/2018 | | |

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|--------------|------------------------|--------------------|------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|----------------|----------------|----------|
| LUTT19-06-36 | Little Canfield Parish | Public Footpaths | B1256 - Little Canfield | Vegetation trimming | clearing foot paths / cutting thorn branches to make accessibility to prams/pushchairs/runners for clear access along the entire b1256 in Little Canfield, there are particular areas eg opposite the entrance to the crumps farm area. | | | | |
| LUTT19-06-05 | Little Dunmow | Tyler Avenue | On walkway off of tyler avenue | OGRO | Ra 4=1x4 RANGERS overgrown bush blocking the footpath and coving 40% of the footway | 3284575 | 12/11/2018 | | |
| LUTT19-05-03 | Little Dunmow | B1256 junction | | | ADHOC JOB - Safety cut at the junction | | | 20/05/2019 | COMPLETE |
| LUTT19-05-11 | Little Easton | Dunmow Road | At Bowyers bridge | Vegetation trimming | ADHOC JOB - Safety cut at the junction | | | 22/04/2019 | COMPLETE |
| LUTT18-10-37 | Little Hallingbury | Gaston Hill | Opp Hop Poles | Vegetation trimming | Bend sign and sub plate. Obscured by vegetation. | 3246741 | 23/07/2018 | 18/02/2019 | COMPLETE |
| LUTT18-10-38 | Little Hallingbury | Lower Road | Jw Hatch Green. | Vegetation trimming | Vegetation obscuring sight line when exiting Hatch Green. | 3246774 | 23/07/2018 | 18/02/219 | COMPLETE |
| LUTT18-08-03 | Little Hallingbury | Goose Lane | Bridge | Vegetation trimming | The vegetation is growing where used to be a pavement | | 30/07/2018 | | |
| LUTT19-06-14 | Little Hallingbury | Gaston Hill | Os Pleasant View. | RSOB | Ra2 = 1 x2. Sign dirty. Rangers | 3365178 | 01/05/2019 | | |
| LUTT19-01-12 | Little Hallingbury | Lower Road | Pavement on Lower Road on the dangerous bend by The Thatch and Brook House (CM22 7RA) | Vegetation trimming | There is a bow of tree going over the pavement and it needs to be cleared as a matter of urgency because if one wants to get past must bend which is dangerous especially in the dark as one can walk into it - which had already happen. Many children use the pavement to walk to school and back so it's important that it's cleared as soon as possible | | 19/11/2018 | | COMPLETE |
| LUTT19-06-20 | Little Hallingbury | Lower Road | Jw George Green Bungalows northl | Other (explain in notes) | Ra2 = 2x1. Aco drain blocked . Approx 8.0m. Rangersl | 3378476 | 06/06/2019 | | |
| LUTT19-06-21 | Little Hallingbury | Lower Road | Jw George green Bungalows. South side. | Other (explain in notes) | Ra2 = 2x1. Aco drain blocked . Approx 7.0m. Rangersl | 3378478 | 06/06/2019 | | |
| LUTT19-06-22 | Little Sampford | Flemings Farm Lane | From junction with great clerks farm till the end of the road | OGRO | Ra4=2x2 overgrown vegetation aprox 500m length encroaching the cw 20% either side roughly job for rangers | 3379413 | 10/06/2019 | | |
| LUTT18-07-27 | Manuden | The Street | Pavement between no 48 & The Yew Tree Inn | Other (explain in notes) | Grill of pavement side drainage gutter requires clearing This work should be scheduled to be done every two years or so. | | 19/06/2018 | | |
| LUTT18-10-07 | Manuden | Mallows Green Road | Outside Catherine Cottages https://goo.gl/maps/Dc6u5Z6acbF2 | Vegetation trimming | The road is regularly used by large/tall farm vehicles and farm delivery lorries. Lorries are struggling to get up the road because of the overhanging trees/branches | | 11/09/2018 | | |
| LUTT19-01-83 | Manuden | The Street | Approx 100m south of jw David Collins Drive. | RSOB | Junction sign obscured by vegetation. as 30mph zone. | 3306921 | 18/12/2018 | | |
| LUTT18-07-28 | Margaret Roding | | REQUEST FOR PARISH VISIT | Other (explain in notes) | Parish Visit contact Parish Clerk, Allison Ward 01245 231798 | | 19/06/2018 | | |
| LUTT18-06-34 | Newport | Farmberry Lane | | Vegetation trimming | Hedge and sign cleaning | | | 11/12/2018 | Complete |

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|---------------------|-----------------------------|------------------------|--------------------------------------------------------------------------------|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|----------------|-------------------|----------------|-----------------|
| LUTT18-06-35 | Newport | Bullfields | Opp Layby | Vegetation trimming | Cutting back of overhanging vegetation | | | 11/12/2018 | Complete |
| LUTT18-06-36 | Newport | Gaces Acre | Next to traffic lights | Vegetation trimming | Cutting back branches from shrubs | | | 11/12/2018 | Complete |
| LUTT18-06-37 | Newport | Cherry Garden Lane | | Sign cleaning | Cleaning street signage and replacing posts | | | 11/12/2018 | Complete |
| LUTT18-06-38 | Newport | Frambury Lane | Top of Fambery Lane | Other (explain in notes) | Straightening of signage | | | 11/12/2018 | Complete |
| LUTT18-06-39 | Newport | School Lane | Opp Wicken Road | Other (explain in notes) | Litter picking and Vegetation trimming | | | 12/12/2018 | Complete |
| LUTT18-06-40 | Newport | Bowkers Close | | Vegetation trimming | Vegetation trimming in three loactions | | | 12/12/2018 | Complete |
| LUTT19-01-10 | Newport | Whiteditch Lane | All along | Vegetation trimming | ADHOC JOB - Cut back the hedge around the bend and along the road with the tractor | PARISH VISIT | | 04/01/2019 | COMPLETE |
| LUTT19-01-11 | Newport | Frambury Lane | all along | Vegetation trimming | ADHOC JHOB - Cut the hedge around the 20mph sign | PARISH VISIT | | 10/12/2019 | COMPLETE |
| LUTT19-01-12 | Newport | Frambury Lane | all along | Vegetation trimming | ADHOC JHOB - clean all signs | PARISH VISIT | | 10/12/2019 | COMPLETE |
| LUTT18-08-15 | Newport | | REQUEST FOR PARISH VISIT | | Christine Griffin - 01799 542541 | | 24/07/2018 | | COMPLETE |
| LUTT18-10-52 | Newport | Gaces Acre | Opposite 56 | Vegetation trimming | veg coming slightly into cw for 20m | 3255508 | 15/08/2018 | 04/12/2018 | COMPLETE |
| LUTT18-10-08 | Newport | High Street | At the junction with Wicken Road | Other (explain in notes) | Please reset the bollard that is currently leaning | | 14/09/2018 | | |
| LUTT18-10-45 | Newport | Hitch Common Road | From house 22 to 18 | Vegetation trimming | weeds growing along the fw covering 25% | 3250592 | 03/08/2018 | | |
| LUTT18-10-57 | Newport | High Street | From junction with frambury lane up to cross mere house | Vegetation trimming | overgrown veg 30m | 3262844 | 11/09/2018 | | |
| LUTT19-01-95 | Newport | London Road | From bowker close to end of 30 limit | FWDF | fw has been sided out by exposing areas of erroded fw, referee to AM for review | 3327589 | 05/02/2019 | | |
| LUTT18-06-26 | Quendon And Rickling | London Road | Jw Rickling Green. | Sign cleaning | Direction signs dirty. | 3223748 | 15/05/2018 | 25/02/2018 | COMPLETE |
| LUTT18-08-07 | Quendon And Rickling | | REQUEST FOR PARISH VISIT | | Sally Kitcat - 07773 305763 | | 17/07/2018 | | |
| LUTT19-05-05 | Quendon And Rickling | Hall Field | all along | Vegetation trimming | ADHOC JOB - Cut the grass away from the path | | | 20/05/2019 | COMPLETE |
| LUTT18-07-31 | Radwinter | throughout the village | | Sign cleaning | All signs in the village need cleaning and possibly straightening | | 14/06/2018 | | |
| LUTT18-10-09 | Radwinter | Wimbish Green Lane | The bend after The Grange | Vegetation trimming | 50 yards away, on the next bend heading towards Wimbish, the undergrowth is concealing the footpath sign and most of the chevrons sign too. | | | | |
| LUTT18-10-10 | Radwinter | Walden Road | by the Plough inn and near the village hall | Sign cleaning | Road Signs need cleaning all signs on the main road need clearing | | 23/06/2018 | | |
| LUTT18-06-50 | Saffron Walden | The Kilns | | Other (explain in notes) | Clear Culvert and Vegetation trimming around the river | | | 29/11/2018 | COMPLETE |
| LUTT18-06-51 | Saffron Walden | Thaxted Road | Opp Lord Butler | Other (explain in notes) | Clear out culvert | | | 29/11/2018 | COMPLETE |
| LUTT18-10-61 | Saffron Walden | Station Road | At junction with south road | Vegetation trimming | 5meters length 10cms into the road 2meters high | 3270503 | 08/10/2018 | 02/05/2019 | COMPLETE |
| LUTT18-10-36 | Saffron Walden | Byrds Farm Lane | At the side of No9 | Vegetation trimming | 15m of overgrown vegetation on the side of the fw work | 3245279 | 18/07/2018 | 15/05/2019 | COMPLETE |
| LUTT18-10-43 | Saffron Walden | Harvey Way | Opposite 117 overgrown veg on right hand side as you come down from Harvey way | Vegetation trimming | overgrown veg 5m | 3249441 | 31/07/2018 | 15/05/2019 | COMPLETE |

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|--------------|----------------|-----------------|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|----------------|----------------|----------|
| | Saffron Walden | Station Road | At junction with south road | OGRO | 5meters length 10cms into the road 2meters high JOB FOR RANGERS | 3270503 | 08/10/2018 | | |
| LUTT19-01-01 | Saffron Walden | Museum Street | Outside Pudding House | Other (explain in notes) | ADHOC JOB - Reset loose kerb | | | 04/04/2019 | COMPLETE |
| LUTT19-01-10 | Saffron Walden | Thaxted Road | Pathway from Thaxted Road to Stanley Farm Road | Vegetation trimming | Overgrown hedgerow | | 09/01/2019 | 02/05/2019 | COMPLETE |
| LUTT19-05-10 | Saffron Walden | Audley End | along the conservation area | Vegetation trimming | ADHOC JOB - Undertake the cut to the conservation area | | | 22/05/2019 | COMPLETE |
| LUTT18-06-27 | Saffron Walden | Audley End Road | Vegetation to the right of the County High Access | Vegetation trimming | Visibility obscured coming out of the access looking right | | 08/06/2018 | | |
| LUTT18-07-35 | Saffron Walden | Newport Road | Saffron Walden | Vegetation trimming | vegetation encroaching onto fway 40m in length, ? | 3238182 | 27/06/2018 | | |
| LUTT18-07-36 | Saffron Walden | Thaxted Road | Saffron Walden | Vegetation trimming | direction sign obscured by vegetation, | 3237596 | 26/06/2018 | | |
| LUTT18-07-37 | Saffron Walden | Ashdon Road | Alongside Tudor Park on the Ashdon side of the roundabout | Vegetation trimming | Crossing Ashdon Road from the dropped kerb on Tudor Park side over to the dropped kerb near De Vigier Ave - when you look right towards Ashdon, visibility is very limited because there's a very bushy hedge and it's on a bend. It's within the 30mph limit but cars can be quite quick round that bend. Trimming the hedge right back would add quite a few meters of visibility | | 14/06/2018 | | |
| LUTT18-07-38 | Saffron Walden | Ashdon Road | Alongside the new footpath that has been built between the corner of De Vigier Ave and the Mortimer Gate development | Vegetation trimming | There are lots of mid-sized trees on the steep bank which drops between the new footpath and Ashdon Road. A few of them got uprooted during the footpath works and are now horizontal and leaning/balancing on the other trees. There is a risk that they could fall down onto the road so should be removed | | 14/06/2018 | | |
| LUTT18-08-01 | Saffron Walden | Castle Street | The section east of the Museum Street junction | Weeding | The trees along the path on the opposite side of the school have large weeds growing at the bottom | | 01/08/2018 | | |
| LUTT18-08-06 | Saffron Walden | Windmill Hill | on the right hand side as you approach Saffron Walden | Vegetation trimming | the vegetation covers up the 30mph sign - needs clearing back | | 18/07/2018 | | |
| LUTT18-08-11 | Saffron Walden | The Cockpit | Outside the Antiques Shop | Other (explain in notes) | Reset loose paving slab | | 14/06/2018 | | |
| LUTT18-09-01 | Saffron Walden | Peaslands Road | on the approach to the old Friends School site | adhoc | Remove the now redundant school warning sign | | 11/09/2018 | | |
| LUTT18-09-02 | Saffron Walden | Debden Road | on the approach to the old Friends School site | adhoc | Remove the now redundant school warning sign | | 11/09/2018 | | |
| LUTT18-10-11 | Saffron Walden | Swan Meadow | The footpath from the golf club passed Water Farm | Vegetation trimming | vegetation is impeding the footpath through to the car park | | 12/09/2018 | | |
| LUTT18-10-44 | Saffron Walden | Catons Lane | By school 30 m from beginning of the road | Vegetation trimming | overgrown vegetation around Virgin boxes | 3250504 | 02/08/2018 | | |
| LUTT19-01-13 | Saffron Walden | Ashdon Road | the verge between the Tudor Park development and the highway. On the left before the roundabout into Saffron Walden from Ashdon direction | Vegetation trimming | The weeds need to be cut back and low growing planting to be installed so that visibility is retained for pedestrians | | 19/11/2018 | | |

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|--------------|-----------------------|------------------|------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|----------------|----------------|------------|
| LUTT19-01-75 | Saffron Walden | Windmill Road | Btwn New Pond Lane and Littlebury turn off. | Vegetation trimming | Vegetation encroaching narrow footway in various locations. | 3282283 | 07/11/2018 | | |
| LUTT19-01-79 | Saffron Walden | Newport Road | Between Walden Lodge and river Fulfen Slade towards SW | OGRO | vegetation encroaching onto fway, 2 kms in length, ? | 3292864 | 21/11/2018 | | |
| LUTT19-01-80 | Saffron Walden | Newport Road | Adjacent to Beeches Close | OGRO | vegetation encroaching onto fway, 0.5 km in length, ? | 3292865 | 23/11/2018 | | |
| LUTT19-01-85 | Saffron Walden | Harris Yard | Opposite 7 | OGRO | overgrown veg 10 metres covering 50% of fw and sign | 3311036 | 03/01/2019 | | |
| LUTT19-06-17 | Saffron Walden | Freshwell Street | By LC9 | OGRO | RA3=1x3 Overgrown Vegetation Impeding Footway JOB FOR RANGERS 15m | 3373146 | 22/05/2019 | | |
| LUTT19-06-19 | Saffron Walden | Ashdon Road | Outside 112, 114 | OGRO | Ra1=1x1 overgrown vegetation encroaching cw by 5% 20m length job for rangers | 3376546 | 03/06/2019 | | |
| LUTT19-06-23 | Saffron Walden | Mill Lane | At lc 1 | OGRO | Ra2=2x1 overgrown vegetation obscuring street light by 20% job for rangers | 3380532 | 12/06/2019 | | |
| LUTT19-06-24 | SAFFRON WALDEN | WINDMILL HILL | BANK ON THE WEST SIDE OF WINDMILL HILL AS YOU LEAVE TOWN | Vegetation trimming | | | | | |
| LUTT19-06-25 | SAFFRON WALDEN | WINDMILL HILL | ROAD SIGNS ALONG WINDMILL HILL | Sign cleaning | | | | | |
| LUTT18-07-40 | Stansted | Stansted Road | The path leading from Pines Hill to the Birchanger roundabout | vegetation trimming | Vegetation encroaching on the footpath for the whole length and pushing pedestrians into the road | | 14/06/2018 | | UNSUITABLE |
| LUTT19-05-04 | Stansted | Jordan Close | | Vegetation trimming | ADHOC JOB - Cut up a tree that was blocking the road | | | 20/05/2019 | COMPLETE |
| LUTT18-07-41 | Stansted | | REQUEST FOR PARISH VISIT | | Ruth Clifford - 01279 813214 | | 20/06/2018 | | |
| LUTT18-07-42 | Stansted | Water Lane | The path leading over the railway bridge towards West Road | Vegetation trimming | vegetation narrowing the path | | 19/06/2018 | | |
| LUTT18-07-43 | Stansted Mountfitchet | Church Road | Stansted Mountfitchet | Vegetation trimming | Vegetation encroaching Fway. | 3234109 | 15/06/2018 | 03/07/2018 | COMPLETE |
| LUTT18-07-44 | Stansted Mountfitchet | Church Road | Stansted Mountfitchet | Sign cleaning | Triangular signs dirty . Road junction and road narrows | 3234108 | 15/06/2018 | 01/11/2018 | COMPLETE |
| LUTT18-10-39 | Stansted Mountfitchet | Rainsford Road | S/o no 21. | Vegetation trimming | buddleigha tree encroaching Fway. | 3247229 | 24/07/2018 | | |
| LUTT18-10-53 | Stansted Mountfitchet | Brook View | Western side for first 20m. Note public footpath parallel to the road. | Vegetation trimming | Vegetation encroaching Cway. Approx 20m. | 3255573 | 16/08/2018 | | |
| LUTT19-06-11 | Stansted Mountfitchet | Church Road | Traffic calming measure, approx 20m nothing of jw Mountfitchet Road. | HWSW | Ra4 = 1 x 4. Water in Cway 15m x 1.2m. Aco drain blocked. Rangers. | 3343470 | 15/03/2019 | | |
| LUTT19-06-12 | Stansted Mountfitchet | Bayford Way | Opp nos 10 to 14. | OGRO | Ra4 = 1 x 4. Hedge encroaching Fway and Cway. Approx 50m. Other side is footpath 24. Rangers. | 3361928 | 25/04/2019 | | |
| LUTT18-10-12 | Stansted North | Gall End Lane | Ugley Brook | Debris clearance | The build up of branches and twigs in the Brook causes the culvert screen at Lower Street to block up on a regular basis increasing the risk of flooding in Lower Street. Please can the rake out and remove the debris which gathers in the bottom of the brook ASAP before the bad weather sets in | | 17/09/2018 | | |

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|--------------|-------------|----------------------------------------------|-------------------------------------------------------------------------------------------------|-----------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|----------------|----------------|----------|
| LUTT18-10-13 | Stebbing | Church End / Brookend Road | opposite Church Farm | Vegetation trimming | around PROW finger post and 30 MPH sign | | 19/09/2018 | | |
| LUTT18-06-28 | Takeley | Gorefeld | On stream bridge next to LC7. | Vegetation trimming | Vegetation obscuring street lamp. | 3226702 | 25/05/2018 | 18/02/2019 | COMPLETE |
| LUTT18-06-29 | Takeley | Waltham Hall Road | Adj jw Parsonage Road . | Sign cleaning | Directional finger post dirty. | 3215312 | 19/04/2018 | 08/10/2018 | COMPLETE |
| LUTT18-07-46 | Takeley | Roding Drive | Takeley | Vegetation trimming | Hedge Overgrown affecting sight lines | 3233918 | 15/06/2018 | 18/02/2019 | COMPLETE |
| LUTT18-07-48 | Takeley | Molehill Green | Jw School Lane | Sign cleaning | Directional finger post sign dirty. | 3231724 | 11/06/2018 | 01/10/2018 | COMPLETE |
| LUTT18-10-40 | Takeley | Dunmow Road | Opp jw Canfield Road. | Vegetation trimming | Vegetation obscuring direction sign. | 3248400 | 27/07/2018 | 19/02/2019 | COMPLETE |
| LUTT18-10-41 | Takeley | Dunmow Road | Pedestrian crossing adj jw Canfield Road. | Vegetation trimming | Vegetation obscuring traffic lights. Pole no 3. | 3248401 | 27/07/2018 | 18/02/2019 | COMPLETE |
| LUTT19-01-87 | Takeley | The Street | Within 30mph limit, east of jw Hatfield Forest Road. | RSOB | Keep left TMP solar bollards x 6 dirty. | 3314230 | 08/01/2019 | 18/03/2019 | COMPLETE |
| LUTT19-01-88 | Takeley | The Street | 30mph limit. West of jw Hatfield Forest Road, | RSOB | Keep left TMP solar bollards x 8 dirty. | 3314229 | 08/01/2019 | 18/03/2019 | COMPLETE |
| LUTT19-01-89 | Takeley | Dunmow Road | East of mini roundabout with Roding Drive. | OGRO | Vegetation encroaching Fway. Approx 15m. | 3314326 | 08/01/2019 | 15/02/2019 | COMPLETE |
| LUTT18-07-49 | Takeley | B1256 | Near the fish and chip shop heading towards the scrapyard | Other (explain in notes) | Bollards need attention as they are protruding and sharp | | 13/06/2018 | | |
| LUTT18-07-50 | Takeley | B1256 | From the telephon exchange to Smiths Green | Vegetation trimming | tree branches are hanging low over the path | | 13/06/2108 | | |
| LUTT19-01-94 | Takeley | Bambers Green Road | Jw Smiths Green Lane, | RSDM | Directional finger post knocked over. | 3327002 | 04/02/2019 | | |
| LUTT19-06-06 | Takeley | The Street | From opp Tudorberry to opp The Rise. | OGRO | Verge vegetation encroaching Fway. Approx 50m x 1. 0m. Rangers. | 3319852 | 17/01/2019 | | |
| LUTT19-06-07 | Takeley | The Street | From opp Lynwood to opp entrance to Joseph Drive | OGRO | Verge vegetation encroaching Fway. Approx 90m x 1. 0m. Rangers. | 3319853 | 17/01/2019 | | |
| LUTT19-06-16 | Takeley | The Street | Bus layby, opp Yew Tree House. | OGRO | Ra4 = 1 x 4. Vegetation obscuring bus stop signand LC43, either side. Total 20m. Rangers. | 3372130 | 20/05/2019 | | |
| LUTT18-06-30 | Thaxted | Holders Green Road | Jw Richmonds Farm Road 2 | Sign cleaning | Finger post direction sign dirty. | 3227277 | 30/05/2018 | 06/12/2018 | COMPLETE |
| LUTT18-07-51 | Thaxted | Newbiggen Street | Thaxted | Sign cleaning | direction sign dirty. | 3233294 | 14/06/2018 | 06/12/2018 | COMPLETE |
| LUTT18-07-52 | Thaxted | Bardfield End Green | Thaxted | Sign cleaning | Directional finger post sign dirty. | 3232420 | 12/06/2018 | 06/12/2018 | COMPLETE |
| LUTT19-01-78 | Thaxted | Monk Street | Jw Folly Mill Lane. | Sign cleaning | Directional finger post sign dirty. | 3290461 | 21/11/2018 | | COMPLETE |
| LUTT18-10-14 | Thaxted | Hanchetts Orchard | Adopted hedgerow on the west side of Hanchetts Orchard | Vegetation trimming | The path running between the hedgerow and adjacent buildings is overgrown. See photograph below. | | 02/10/2018 | 03/12/2018 | COMPLETE |
| LUTT18-10-15 | Thaxted | Town Street at the Junction with Park Street | On the pavement outside the Butchers in Town Street and outside the hairdressers in Park Street | Footway drainage channel cleaning | The pavement gully grid is blocked with soil and weeds at this junction both in Town Street and Park Street. Being situated at the lowest point in the Town this location frequently floods with heavy rainfall. See photographs Below | | 12/09/2018 | 19/11/2018 | COMPLETE |

| REF | Parish/Ward | Road Name | Location | Type of Work Required | Comments | Confirm Number | Date Requested | Date Completed | STATUS |
|--------------|----------------|------------------|-------------------------------------------|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|----------------|----------------|----------|
| LUTT18-10-16 | Thaxted | Church Hall Path | Between Margaret Street and Vicerage Mead | Vegetation trimming | The path running between Margaret Street and Vicerage Mead, beside the Church Hall is restricted by hedging and vegetation encroaching on and over the path, which includes a large amount of Ivy that is obstructing the street light. See photograph below | | 12/09/2018 | 03/12/2018 | COMPLETE |
| | Thaxted | Monk Street | Jw Folly Mill Lane. | RSOB | Ra2 = 1 x2. Directional finger post sign dirty. Rangers. | 3290461 | 21/11/2018 | | |
| LUTT18-10-67 | Thaxted | Mill End | Jw Bardfield Road, | Sign cleaning | Directional road sign dirty. | 3274829 | 22/10/2018 | 06/12/2018 | COMPLETE |
| LUTT19-05-06 | Thaxted | Park Street | at the junction | Vegetation trimming | ADHOC JOB - Cut the grass away from the path | | | 20/05/2019 | COMPLETE |
| LUTT19-05-07 | Thaxted | Park Street | by the Scout hut | Vegetation trimming | ADHOC JOB - Cut the grass away from the path | | | 22/05/2019 | COMPLETE |
| LUTT19-01-81 | Thaxted | Park Street | Opp Garden House. | Sign cleaning | bend and road narrows signs dirty. | 3293839 | 26/11/2018 | | |
| LUTT19-06-03 | Thaxted | Mayes Place | Front of house number 9 | OGRO | RA1= 1x1 RANGERS Moss on pathway covng 80% of the footway | 3271345 | 10/10/2018 | | |
| LUTT18-07-53 | Ugley | Pound Lane | HFT Bradbury Centre | Vegetation trimming | Vegetation restricting sight line | | 22/06/2018 | | |
| LUTT19-01-17 | Ugley | Bedwell Road | along by the bedwell cotages | Vegetation trimming | | | 19/08/2018 | | |
| LUTT19-06-15 | Ugley | London Road | Jw Vicarage Lane. | RSDM | Ra2 = 1 x2. Directional finger post sign dirty. Note split post. Rangers. | 3365790 | 07/05/2019 | | |
| LUTT19-06-13 | White Roding | Poplars Lane | Jw Elms Cottages. | RSOB | Ra4 = 1 x4. Directional finger post sign corroded. Rangers. | 3363882 | 01/05/2019 | | |
| LUTT18-07-54 | Wicken Bonhunt | Wicken Road | Entry and Exit to Village | Sign cleaning | Entry and Exit "Welcome" Signs | | 16/06/2018 | 21/11/2018 | COMPLETE |
| LUTT18-07-57 | Wicken Bonhunt | Wicken Road | The Meads Bank | Grass | Grass cutting bank | | 16/06/2018 | 20/02/2019 | COMPLETE |
| LUTT18-07-55 | Wicken Bonhunt | Wicken Road | The Meads Lane | Vegetation trimming | Hedge to entrance lane of The Meads | | 16/06/2018 | | |
| LUTT18-07-56 | Wicken Bonhunt | Wicken Road | Along the Wicken Water edge | Painting | White rail along Wicken Water's edge | | 16/06/2018 | | |
| LUTT18-06-33 | Wimbish | Mill Road | Jw Maple Lane. | Sign cleaning | Directional finger post sign dirty. | 3227964 | 04/06/2018 | 24/04/2019 | COMPLETE |