

Sheering Mill Bridge No. 451 Bore holes

Soil investigation work was required to the River Stort prior to the permanent works at Sheering Mill Bridge.

The structures team organised for the soil investigation to be carried out, this was done by drilling 3 boreholes into the River Stort for confirmation of the soil condition. These findings were then included in a report which enables the team to develop the permanent works design.



Borehole testing work